

### ***Botanical surveys***

Norris Bridge is the boundary between western and eastern parts.

2008 All off-channel areas  
2009 Western part of canal  
2010 No monitoring  
2011 Eastern part of canal  
2012 Western part of canal  
2013 Eastern part of canal  
2014 All off-channel areas  
2015 Western part of canal  
2016 Eastern part of canal  
2017 No monitoring  
2018 Western part of canal  
2019 Eastern part of canal

### ***Dragonfly surveys***

No formal arrangement. The BCA will liaise with the Wildlife Trusts, Ministry of Defence contacts and local naturalists expert on dragonflies, collecting and collating survey results as they become available and presenting them for assessment at January review meetings. If Natural England requires more than is yielded by these processes for its periodic condition assessment of the SSSI, it will commission the necessary survey.

### ***Other data***

The collection and assessment of other data components is covered in Section 3 above.

Water level	<b>WL.2 WL.5</b>
Water quality	<b>WQ.7</b>
Tree management	<b>TR.2</b>
Navigation	<b>NV.1 NV.2</b>
Fisheries and angling	<b>FA.3</b>
Dredging	<b>DR.5</b>
Bank protection	<b>BP.3</b>
Vegetation control	<b>VC.4</b>
Bankside vegetation	<b>BV.3</b>
Non-native species	<b>NN.6</b>
Greywell Cutting	<b>GC.1</b>
Off-channel areas	<b>OC.1</b>
Higher Level Stewardship Projects	<b>HLS</b>

<b>Year</b>			
<b>2011</b>	<b>Year targets</b>		
	Water quality	<ul style="list-style-type: none"> <li>Plan depth survey – BCA / S&amp;HCS</li> </ul>	WQ.3
		<ul style="list-style-type: none"> <li>Plan feasibility studies for additional water supplies and storage capability</li> </ul>	WQ.6
		<ul style="list-style-type: none"> <li>Report on non-native species</li> </ul>	NN.6
	Tree management	<ul style="list-style-type: none"> <li>Collate all tree survey data and finalise tree management plan for ongoing actions</li> <li>Start HLS projects as per agreed project plan for Surrey</li> </ul>	TR.1 HLS
	Navigation	<ul style="list-style-type: none"> <li>Install boat counters if funding permits</li> </ul>	NV.1
		<ul style="list-style-type: none"> <li>Update literature on boat speed and licence requirements / controls (open navigation access policy)</li> </ul>	NV.3
	Bank protection	<ul style="list-style-type: none"> <li>Term contract to start on bank revetment programme (2011 -2013)</li> <li>Special (HLS) Projects as per agreed project plan for Surrey</li> </ul>	BP.3 HLS
	Greywell Cutting	<ul style="list-style-type: none"> <li>As per TR.1 and subject to HLS application for Hampshire</li> </ul>	GC.1 HLS
	Botanical survey	<ul style="list-style-type: none"> <li>Easter part of canal (as not completed in 2010)</li> </ul>	4.1
<b>2012</b>	<b>January CSG review</b>		
	HLS Project	<ul style="list-style-type: none"> <li>Report on programme for 2011 and year ahead</li> </ul>	
	Botanical survey	<ul style="list-style-type: none"> <li>Assess results for eastern part of canal</li> </ul>	4.1
	Water quality	<ul style="list-style-type: none"> <li>Assess results from water depth survey (2011)</li> </ul>	WQ.3
		<ul style="list-style-type: none"> <li>Plan turbidity survey</li> </ul>	WQ.3
		<ul style="list-style-type: none"> <li>Install basic telemetry for water level control and monitoring</li> </ul>	WQ.6
<b>2012</b>	<b>Year targets</b>		
		<ul style="list-style-type: none"> <li>Assess pollution response capability</li> </ul>	WQ.5
		<ul style="list-style-type: none"> <li>Complete turbidity survey</li> </ul>	WQ.3
	Tree management	<ul style="list-style-type: none"> <li>Assess tree management plan and review</li> </ul>	TR.1
		<ul style="list-style-type: none"> <li>Plan tree survey</li> </ul>	HLS
		<ul style="list-style-type: none"> <li>Select lengths for management in 2013/14</li> </ul>	TR.2
	Navigation	<ul style="list-style-type: none"> <li>Report on boat speed and logging</li> </ul>	NV.3

		<ul style="list-style-type: none"> <li>Review mooring/turning places</li> </ul>	NV.4
	Bank protection	<ul style="list-style-type: none"> <li>Review progress of repair works on banks, develop future programme of work and allocate resources</li> </ul>	BP.3
	Botanical Survey	<ul style="list-style-type: none"> <li>Western part of canal</li> </ul>	4.1
	Non-native species	<ul style="list-style-type: none"> <li>Review eradication of Parrot's feather and report</li> </ul>	NN.3
	Greywell Cutting	<ul style="list-style-type: none"> <li>Continue to manage trees and report on any further work required</li> </ul>	GC.2
	Off-channel areas	<ul style="list-style-type: none"> <li>Survey state and decide work priorities</li> </ul>	OC.1
		<ul style="list-style-type: none"> <li>Start HLS funded projects</li> </ul>	HLS
	Water quality	<ul style="list-style-type: none"> <li>Complete turbidity survey</li> </ul>	WQ.3
<b>2013</b>	<b>January CSG review</b>		
	Water quality	<ul style="list-style-type: none"> <li>Report results of turbidity survey and proposed actions.</li> </ul>	WQ.3
		<ul style="list-style-type: none"> <li>Report pollution response capability and any proposed developments to improve capability</li> </ul>	WQ.5
		<ul style="list-style-type: none"> <li>Assess results for western part of canal</li> </ul>	
	Tree management	<ul style="list-style-type: none"> <li>Report on tree management programme</li> </ul>	TR.2
	Navigation	<ul style="list-style-type: none"> <li>Review further proposals for mooring/turning places</li> </ul>	NV.4
	Bank protection	<ul style="list-style-type: none"> <li>Review progress of repair works on banks, develop future programme of work and allocate resources</li> </ul>	BP.3
	Non-native species	<ul style="list-style-type: none"> <li>Report on eradication of Parrot's feather</li> </ul>	NN.3
		<ul style="list-style-type: none"> <li>Report on other non-native and invasive species</li> </ul>	NN.5 NN.7 NN.8
	Off-channel areas	<ul style="list-style-type: none"> <li>Report state of areas and proposed work programme</li> </ul>	OC.1 HLS
<b>2013</b>	<b>Year targets</b>		
	Water quality	<ul style="list-style-type: none"> <li>Implement agreed turbidity controls.</li> </ul>	WQ.3
	Tree management	<ul style="list-style-type: none"> <li>Review tree management programme</li> </ul>	TR.2 HLS
	Navigation	<ul style="list-style-type: none"> <li>Establish agreed further mooring/turning places</li> </ul>	NV.4

	Bank protection	<ul style="list-style-type: none"> <li>Continue programme of repair works in unshaded locations</li> <li>Review term contract</li> </ul>	BP.3 BP.4 BP.6
		<ul style="list-style-type: none"> <li>Plan further programme of repair works as required</li> </ul>	BP.5
	Botanical survey	<ul style="list-style-type: none"> <li>Eastern part of canal</li> </ul>	
	Off-channel areas	<ul style="list-style-type: none"> <li>Start HLS work programme</li> </ul>	OC.1 HLS
<b>2014</b>	<b>January CSG review</b>		
	Water quality	<ul style="list-style-type: none"> <li>Report progress with turbidity controls. Carry forward as required.</li> </ul>	WQ.3
		<ul style="list-style-type: none"> <li>Report on water storage and supply options</li> </ul>	WQ.6
	Botanical survey	<ul style="list-style-type: none"> <li>Assess results for Eastern part of canal</li> </ul>	4.1
<b>2014</b>	<b>Year targets</b>		
	Bank protection	<ul style="list-style-type: none"> <li>Complete programme of repair works in shaded locations</li> </ul>	BP.5
	Botanical survey	<ul style="list-style-type: none"> <li>All off-channel areas</li> </ul>	
	<i>Second Periodic Review of CMP</i>	<i>Review progress 2011-2013 and set targets to 2016</i>	<i>4.3</i>